

File Ref: BUR1501

7 August 2015

Brett Oldfield  
Combustion Control Ltd  
PO Box 13-454  
Onehunga  
**Auckland 1643**

Dear Brett

**Burner Renewal**

I am pleased to advise that your application for the following burners has been approved.

BUR1501 – MAXFLAM (models as submitted)

A copy of the approval is attached. The approval will be recorded in the register of approved burners on the website of WorkSafe New Zealand.

Please take note of all the conditions attached to the approval. These conditions may be different from earlier approvals as changes have been made over time.

Yours sincerely



Dick Burgess  
Advisor  
**Certifications, Approvals and Registrations Team**

## DECISION

Under Clause 68 of Schedule 8 of the Hazardous Substances (Dangerous Goods and Scheduled Toxic Substances) Transfer Notice 2004, the Authority may approve a burner for the combustion of class 3.1 substances.

Burners	
Register Number	BUR1501
Application Type	New approval
Applicant	Combustion Control Ltd
Burner type	Ecoflam Bruciatori S.p.A.
Model Numbers	MAXFLAM 10, 20, 30, 30AB, 50AB

## Approval


This application for Ecoflam Bruciatori S.p.A. MAXFLAM heavy oil burners manufactured by the Burners Division of Ariston Thermo Group of Italy with model numbers 10, 20, 30, 30AB, 50AB is approved subject to any importer or supplier of these burners ensuring the following:

### Conditions

1. Each purchaser of a Ecoflam Bruciatori S.p.A. MAXFLAM 10, 20, 30, 30AB, 50AB burner must be provided with a copy of the Ecoflam Bruciatori S.p.A. manufacturer's operating and maintenance instructions.
2. The register number BUR1501 must be fixed to each Ecoflam Bruciatori S.p.A. MAXFLAM 10, 20, 30, 30AB, 50AB burner in a manner that will ensure it will remain legible for the life of the burner under the conditions in which the burner is installed and operated.
3. A plate stating that fuels to be used must be fixed to each Ecoflam Bruciatori S.p.A. MAXFLAM 10, 20, 30, 30AB, 50AB burner in a manner that will ensure it will remain legible for the life of the burner under the conditions in which the burner is installed and operated.

4. The importer or supplier of a listed Ecoflam Bruciatori S.p.A. MAXFLAM 10, 20, 30, 30AB, 50AB burners must advise the Manager Certifications, Approvals and Registrations, High Hazards and Specialist Services at WorkSafe New Zealand if a burner develops faults or fails in service due to product malfunction, defective manufacturer's workmanship or design failure that could render the equipment unsafe or lead to unsafe burner operating conditions.
5. This approval is invalidated for a Ecoflam Bruciatori S.p.A. MAXFLAM 10, 20, 30, 30AB, 50AB burner if there are any changes to the design of that model of Ecoflam Bruciatori S.p.A. oil burner.
6. The import or supply of Ecoflam Bruciatori S.p.A. MAXFLAM 10, 20, 30, 30AB, 50AB burner remains valid for 5 years from the date of this approval.

Taking into account the factors listed above, I am satisfied that the application meets the prescribed requirements.

  
George Hewitt

Date:

06 August 2015

Principal Advisor  
Hazardous Substances

#### **Disclaimer**

This approval relates solely to a burner in accordance with Clause 68 of Schedule 8 of the Hazardous Substances (Dangerous Goods and Scheduled Toxic Substances) Transfer Notice 2004.

This approval does not obviate the need for the person in charge to ensure compliance with other relevant aspects of HSNO legislation and related regulations, or other legislation including, but not limited to, the Resource Management Act, the Building Act, Health and Safety in Employment Act, and any local authority requirements.