

File Ref: BUR1002

4 May 2015

Brett Oldfield  
Combustion Control Ltd  
PO Box 13-454  
Onehunga  
**Auckland 1643**

Dear Brett

**Burner Renewal**

I am pleased to advise that your application the renewal the following burner has been approved.

BUR1002 – Ecoflam Max (models as submitted)

A copy of the approval is attached. The renewal will be recorded in the register of approved burners on the website of WorkSafe New Zealand.

Please take note of all the conditions attached to the approval. These conditions may be different from the original approval as changes have been made over time.

Yours sincerely



Dick Burgess  
Advisor  
**Certifications, Approvals and Registrations Team**

## DECISION

Under Clause 68 of Schedule 8 of the Hazardous Substances (Dangerous Goods and Scheduled Toxic Substances) Transfer Notice 2004, the Authority may approve a burner for the combustion of class 3.1 substances.

Burner	
Register Number	BUR1002
Application Type	Renewal
Applicant	Combustion Control Ltd
Burner type	Ecoflam Bruciatori S.p.A.
Model Numbers	MAX 1, 1R, 4, 4R, 8, 12, 15, 20, 25, 30, P 35 AB & P 45 AB

## Approval

This application to renew Ecoflam Bruciatori S.p.A. oil burners MAX 1, 1R, 4, 4R, 8, 12, 15, 20, 25, 30, P 35 AB & P 45 AB manufactured by Ariston Therma SPA of Italy is approved subject to any importer or supplier of these burners ensuring the following:

### Conditions

1. Each purchaser of a Ecoflam Bruciatori S.p.A. oil burner MAX 1, 1R, 4, 4R, 8, 12, 15, 20, 25, 30, P 35 AB or P 45 AB must be provided with a copy of the Ecoflam Bruciatori S.p.A. manufacturer's operating and maintenance instructions.
2. The register number BUR1002 must be fixed to each Ecoflam Bruciatori S.p.A. oil burner MAX 1, 1R, 4, 4R, 8, 12, 15, 20, 25, 30, P 35 AB or P 45 AB in a manner that will ensure it will remain legible for the life of the burner under the conditions in which the burner is installed and operated.
3. A plate stating that only diesel including low flash point diesel is to be used in the burner must be fixed to each Ecoflam Bruciatori S.p.A. oil burner MAX 1, 1R, 4, 4R, 8, 12, 15, 20, 25, 30, P 35 AB or P 45 AB in a manner that will ensure it will remain legible for the life of the burner under the conditions in which the burner is installed and operated.

4. The importer or supplier of a listed Ecoflam Bruciatori S.p.A. oil burner MAX 1, 1R, 4, 4R, 8, 12, 15, 20, 25, 30, P 35 AB or P 45 AB must advise the Manager Technical Services at WorkSafe New Zealand if the burner develops faults or fails in service due to product malfunction, defective manufacturer's workmanship or design failure that could render the equipment unsafe or lead to unsafe burner operating conditions.
5. This approval is invalidated for a Ecoflam Bruciatori S.p.A. oil burner model MAX 1, 1R, 4, 4R, 8, 12, 15, 20, 25, 30, P 35 AB or P 45 AB if there are any changes to the design of that model of Ecoflam Bruciatori S.p.A. oil burner.
6. The import or supply of Ecoflam Bruciatori S.p.A. oil burner model MAX 1, 1R, 4, 4R, 8, 12, 15, 20, 25, 30, P 35 AB or P 45 AB remains valid for a period not exceeding 5 years from the date of this approval.

Taking into account the factors listed above, I am satisfied that the application meets the prescribed requirements.



---

Richard Steel

Date: 4/5/15

Manager

Technical Support Services

#### Disclaimer

This approval relates solely to a burner in accordance with Clause 68 of Schedule 8 of the Hazardous Substances (Dangerous Goods and Scheduled Toxic Substances) Transfer Notice 2004.

This approval does not obviate the need for the person in charge to ensure compliance with other relevant aspects of HSNO legislation and related regulations, or other legislation including, but not limited to, the Resource Management Act, the Building Act, Health and Safety in Employment Act, and any local authority requirements.